

Renew

6/5  
7/8

T315 R2W

Found

30" D. Fir now 35" N31E 33°  
Shows good scar

16" Cedar now 16" N40W 33°  
Shows good scar

36" D. Fir now down S72E 37°  
Some pitched over scribbling visible

No trace of S.W. BT

Also

Brass cap at sec cor MKD.

General land office

T315 R2W

56/55  
57/58

1918

DIETZGEN NO. 385-6

New Bearing Trees

38" D. Fir S45W 91°  
Scribbled T315 R2W S72E BT

32" D. Fir S61E 79°  
Scribbled T315 R2W S8 CS BT

6-20-69

O.K.  
T.W.D.

79

C. S. File No. 54/36-13