

Revised 22/23 27/26 T315 RBW

Found

(Ox. R)

15" D. Fir N40W 24" N10W 10 6
Scribe visible "B"

19" D. Fir N40W 22" S32W 42 2 (Rec S35W)
Tree Burnt No Scribe

12" D. Fir N40W 19" S55SE 15 3 (Rec 17 3)
Scribe visible "J" "BT"

19" D. Fir N40W 17" N68E 21 2 (Rec N70E 29 2)
No Scribe visible

Also Cor Stone firmly in place
with 2 notches on the East

Revised

Set Brass cap of Sec cor along side
stone mark.

County Surveyors office

T315 RBW

522/523
527/526

1970

Reblazed & Rescribed

29" D. Fir N40W 10 6
Scribed T315 RBW 522 CS BT

22" D. Fir S32W 72 2
Scribed T315 RBW 527 CS BT

19" D. Fir S55SE 15 3
Scribed T315 RBW 526 CS BT

19" D. Fir N68E 21 2
Scribed T315 RBW 523 CS BT

3-29-70

JUNE

1970

54/36-39

459

J.W.B.

C.S. File No. 54/36-39

DIETZGEN NO. 385-6