

Renewal 57/58 T.315 RBW

Found

G.L.O. Brass cap at $\frac{1}{4}$ cor M.D.
U.S. Dept of Interior,

$\frac{1}{4}$ 57/58

1962

orig

cedar N 90 W 19" N 67 W 14"
Scribe visible but faint $\frac{1}{4}$ S

New BTs

3 1/2" D. Fir N 90 W 22"
This tree has about half of
top broken out
Scribe visible "1/4 57 BT"

12" D. Fir S 65 W 27"
Shows pitched over scribing
not legible

Renewed

New Bearing Tree

3 1/2" D. Fir S 59 W 26"
Scribed $\frac{1}{4}$ 57 25 BT

2-7-67
J.W.B.
C.S.

* #50 ✓
O.H. J.W.B.

C. S. File No. 54/36-47

DIETZEN NO. 385-6