

Renewal 510 | 511  
515 | 514 T315 RBW

Found:

G.L.O. Brass cap at sec cor

T315 RBW

510 | 511  
515 | 514

1961

11" W. Fir S35W 21 1/2

Shows good scars

NOT 8" W. Fir S34W 22 1/2

Scribed visible "T315 RBW"

NOT 12" W. Fir S36E 18 1/2

Scribed visible T315 RBW S11 BT

NOT 12" W. Fir N20E 15 1/2

Scribed visible N24E 15 1/2

orig 10" Cedar now down N72W 21 1/2

good scars

Renewal:

New Scaring Tree

28" plank N58W 40°

Scribed T315 RBW S10 CS BT

1-26-67

~~21 1/2~~  
~~22 1/2~~  
C 10 1/2

K. J. W. B.

C. S. File No.

54/36 48

DIETZEN NO. 3885-6