

SECTION CORNER BETWEEN 29, 30, 31, 32

T31S RBW

Found:

30" D FIR NOW 38" N30^E 29⁶
 CHECKS FOR ORIG BEARING & DISTANCE
 I DO NOT FIND SCRIBED

36" D FIR 550^E 26²
 NOW SNAIL, CHECKS FOR ORIG. BEARING
 & DISTANCE

12" LAUREL NOW 30" S65^E 29⁰
 CHECKS FOR ORIG BEARING & DISTANCE.
 THE FACE IS ROTTED OUT.

36" D FIR NOW 44" N73^W 21²
 SHOWS FAINT BUT DEFINITE BARK
 SCRIBE (S, B, S)

SET: BRASS CAP MKD.

COUNTY SURVEYORS OFFICE

T31S RBW

530	529
531	532

1967

NEW BTS:

6" D FIR N64^E 21²

MKD: T31S RBW 529 CS BT

I RE SCRIBED

44" D FIR N73^W 21²

MKD: T31S RBW 530 CS BT

ORIG BT

16" D FIR S11^W 46⁴

MKD T31S RBW 531 CS BT

15" D FIR S17^E 49²

MKD: T31S RBW 532 CS BT

NOTE: THIS CORNER LIES 100' WEST
 & 200' NORTH APPROX, OF HAYES FURT
 CREEK.

1-13-66 GCS

#39
 O.K. J.W.B.

C. S. File No. 54/36-54

DIETZGEN NO. 385-6

FILED
RECEIVED

JAN 16 1967

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.