

Renewal

529/328

TJIS RBW

Found:

13" Fir Now Stump S80 E 29°  
Bark scribed 1/4 visible

16" Fir Now Stump S25 W 8°  
Nothing visible on this Tree

I Find This Bearing to be N82W  
Past at cor.  
No Trace of Stone at cor,

Using 2 Distances & 1 Bearing I  
Revised

Renewal:

Set Brass cap at 1/4 cor 18th  
county surveyors office

TJIS RBW

1/4 529/328

1967

New Bearing Trees

14" Chingupia S8W 56°  
Scribed 1/4 529 as BT

18" Cedar S59 1/2 E 112°  
Scribed 1/4 528 as BT

This cor lies about 10° North of  
5th Rd & 130° South of Draw.

1-9-66

*[Signature]*  
1966  
C.S.

\*31 o.k. J.W.B.

C. S. File No. 54/36-61

DIETZGEN NO. 385-6

**FILED**  
**RECEIVED**

JAN 9 1967

**COUNTY SURVEYOR**  
**DOUGLAS COUNTY, ORE.**