

Renewal

$\frac{32}{5}$

T 31 S R 7 W
T 32

Found:

35" D. Fir cor Tree Now snag
 $\frac{1}{4}$ S Faint Bark scribe on
South side of Tree.

32" D. Fir Now 38" N 80 W 13⁰
No scribe found.

36" Cedar Now 38" S 85 E 29⁰
Faint Bark scribe $\frac{1}{4}$ S.

good dist far call on
top of Bridge approx 660' ft.

Renewal

Set Brass cap on West side of
cor Tree M.A.D.
county Surveyors office

T 31 S R 7 W

$\frac{1}{4}$ $\frac{532}{55}$

T 32 S

1969

New Bearing Trees

19" Cedar S 55 W 17⁰
Scribed $\frac{1}{4}$ S 55 CS RT

18" D. Fir N 20¹/₂ E 26⁰
Scribed $\frac{1}{4}$ S 32 CS RT

7-1-69

[Handwritten signature]

o.k. W.B.
#81-131-7
#93-T32-70

C. S. File No. 54/36-44

DIETZEN NO. 385-6