

General

25/30
36/31

T32S R7-RW

Found
OBT's

28" cov tree now rotten stab

20" Fir now stab S70E 78⁰
No scribing

18" Fir now burnt stab S10W 47⁰
Best scribe found T3 RBW BT

10" Fir now stab N82W 66⁰
Found scribe marks but not legible

Dist to BTs appear to be slope
Dist.

General

Set brass cap on South Edge of car
tree stab, MKD

county surveyors office

T32S

R
S 25/30 1
W 36/31 W 7

1967

New Bearing Trees

8" D. Fir East 15⁰
Scribed T32S R7W S30 CS BT

8" D. Fir S78E 16⁰
Scribed T32S R7W S31 CS BT

9" D. Fir N34W 3⁰
Scribed T32S RBW S25 CS BT

10" Laurel S 9 W 25⁰
Scribed T32S RBW S36 CS BT

Note: This car lies approx. 30' south of
High Point Point.

11-7-67

#47-132-7

O.K. J.W.B.

#06-782-8

C.S. File No. 54/36-93

FILED

RECEIVED

NOV 7 1967

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.