

323 | 324
326 | 325

Renew Sec. Cor. T325 R7W

Fd. O.B.T.s as follows -

Orig. 10" Now 21" FIR N. 18° E. 11 1/2 ft.

2 live - shows good axe SCAR - we

Rescribe - "T325 R7W 524 CS BT"

Orig. 16" Now 30" FIR S. 45° E. 46 1/2 ft.

2 live - BARK scribe visible - poor

we Rescribe "T325 R7W 525 CS BT"

Other O.B.T.s gone - 2 + cor. point

set 1" I.P. & BRASS cap MKd. COUNTY

SURVEYORS OFFICE 1970 T325

523 | 524
526 | 525 R7W" & MK. New B.T. -

40" D. FIR N. 22° W. 42 1/2 ft.

Mkd. "T325 R7W 523 CS BT"

No suitable trees close in

Sec. 26 - This cor. lies on

Very steep N.E. slope in

scattered oldgrowth FIR & Dense

chinguipin & Laurel brush.

March 11, 1970

VRT

JGH

VDP

J.R. Tracy

D.H.
J.W.B.

#99

C.S. File No.

54/36-108