

Renewal

$\frac{1}{12}$

T295 RBW

Found:

36" Fir Now Stump N59E 13 $\frac{3}{4}$

16" Fir Now Down N71W 33 $\frac{1}{2}$
shows good scar

12" Maple Now 16" S39E 31 $\frac{1}{2}$
shows good scar

Brass cap at $\frac{1}{4}$ sec cor MKD

General Land office Survey
T295 RBW

$\frac{1}{4}$ $\frac{1}{12}$

1924

11" Maple Scribed $\frac{1}{4}$ S165 N18E 37 $\frac{5}{8}$
BT

17" D. Fir Scribed $\frac{1}{4}$ S12 S86W 23 $\frac{1}{2}$
CS BT

11-29-66

~~J. M. P.~~
~~B. J. P.~~
~~C. J. P.~~

DIETZEN NO. 385-6

Q #126

C. S. File No. 54/38 9