

Renewal # 19 33 T28 RBW
72 7 729 RBW

Found:

48" D. Fir Now Down 190E 2.6
Bark scribe visible "1/2"

48" D. Fir stump 565W 198
"B" visible

10" R. Cedar Now 12" 538E 37 1/2
scribe visible "295 RBW 1/2 of C"

Note: When NE BT Fall it
pulled out Brass cap.

Renewal

Reset Brass cap at 1/4 cor M&D
County Surveyors Office

7283 RBW

4 533
59
329
1957

New Bearing Tree

12" R. Fir N 50W 11 1/2
scribed 1/4 533 to BT

PS Note: This cor lies approx
90° West of small creek

8-21-69

D. W.
J. W. M.

J. W. M.
J. W. M.

#141-728-20

#148

C. S. File No. 54/30-23