

Review $\frac{1}{4}$ cor. $\frac{513}{524}$ T295 R8W

Fd. 1924 G.L.O. BRASS cap in place

Mkd " $\frac{1}{4}$ $\frac{513}{524}$ " & C.B.T.s 25 follows -

1924-30" FIR S. 53° W. 17 $\frac{1}{2}$ ft

Now Badly Decayed - Find scribe & Reverse -

1924-36" FIR N. 73° W. 38 $\frac{1}{2}$ ft.

Now Stamp - scribe visible -

Both orig B.T.s also in evidence - But

Badly decayed with BARK mostly

gone - We MARK new B.T.s

11" D. FIR N. 83° W. 20 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 513 c 5 BT "

8" D. FIR S. 60° W. 17 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 524 c 5 BT "

5" D. FIR S. 88° E. 12 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 524 c 5 BT "

This cor. lies on steep

westerly slope in dense

2nd growth - old cutting line

Bears North approx. 200 ft.

July 22, 1970

VRT
VDP
J.W.R.

W. R. Fray

151

C. S. File No.

DIX.
J.W.R.
543P-26