

Renewal # 142
#83-730-8

536
ONLY

T295
T303 RBW

Found:

Brass cap MKD

county surveyors office

T295 RBW

$\frac{1}{2}$ 536
T303
1967

out of position due to logging

6" W. Fir now 7" N4E 31²

shows good skew

15" Cedar now high stump S11E 20²

Scribe visible

Renewal

Reset Brass cap at $\frac{1}{4}$ cor

New Bearing Tree

11" Cedar N89E 112²

scribed $\frac{1}{2}$ 536 as BT

#158-729-8

7-5-72

#100-730-8

C.S. File No. 54/38-33
C.K. [Signature]

gmm

DIETZGEN NO. 388-1-B