

Renew  $\frac{1}{4}$   $\frac{527}{534}$  TR65 R2W

Fd. 1916 G.L.O. BRASS cap at cor. in  
good cond. & properly MKd. & B.T. as  
follows -

16" now 18" Hemlock S,  $10^{\circ}$ E,  $4\frac{1}{2}$  ft,  
alive - healed Blaze - we don't open  
10" now 16" Hemlock N,  $17^{\circ}$ W,  $10\frac{1}{2}$  ft,  
alive - chopped open several years  
past - shows " $\frac{1}{4}$  527 BT" scribe  
face Beginning to Rot. - We MK. new BT -  
14" Hemlock N,  $51^{\circ}$ E,  $15\frac{1}{2}$  ft,  
MKd. " $\frac{1}{4}$  527 CS BT"

The N.W. cor. of Shively Mt.,  
Look out Tower BEARS S,  $25^{\circ}$ E.

Note. The N.W. B.T. MKd. in 1916 is  
also a B.T. MKd. in 1909 by Gibbs &  
still shows. scribe ~~face~~ - Gibbs  
other B.T. is now BROKEN STAMP.

July 5, 1967

*[Handwritten signature]*

#4 / O.K. J.W.B. C.F. No. 54