

519 | 520

Renew Sec. Cor. 530 | 529 T265 R2W

Fd. Orig. 6" X 11" X 14" Cor. Stone MKd.
with 5 notches on E. & 2 notches on
S. edges & O.B.T.S as follows -

Orig. 4" Now 17" Laurel S 63° E. 39 ¹/₂ ft.
2 live - we open - center Rotted - No scribe.

Orig. 4" Now 15" Maple S. 18° W. 34 ³/₄ ft.
2 live - showed scar - we open - center

Rotted - No scribe. Bearing should be S. 13° W.
Orig. 4" Now 16" Laurel N. 6° W. 28 ¹/₂ ft.

2 live - we open - center Rotted No scribe.
No Trace O.B.T. to N.E. Set 1" I.P.

& BRASS cap MKd. COUNTY SURVEYOR'S
OFFICE 1967 T265 ^{519 | 520} _{530 | 529} R2W"

in place of cor. Stone & MK. New B.T.S -
9" Laurel S. 12° E. 28° ft.

Mkd. T265 R2W S29 CS BT"

8" chinquapin S. 52° W. 13 ¹/₂ ft.

Mkd. T265 R2W S30 CS BT"

9" chinquapin N. 49° W. 34 ³/₄ ft.

Mkd. T265 R2W S19 CS BT"

18" Pine N. 76° E. 31 ¹/₂ ft.

Mkd. T265 R2W S20 CS BT"

This cor. Lies on moderate SE slope.

July 17, 1967 9/ R. Tracy

VRT
J.H.
17

O.K. J.W.D. C.S. File No. 54/17