

Review $\frac{1}{4}$ $\frac{525}{536}$ T265 R2W

Fd. 1916 G.L.O. BRASS CAP MKD.

" $\frac{1}{4}$ $\frac{525}{536}$ " & O.B.T. as follows -

1916 10" NOW 13" Laurel N. 24° E, 11² ft.

2 live - scribe MKs visible on
nearly healed blaze. 1916 SW, BT
gone, only shattered stump remains.

we mk. new B.T.'s -

8" D. FIR N. 6° E, 4⁴ ft.

Mkd. " $\frac{1}{4}$ 525 CS BT"

8" D. FIR S, 7° W, 14² ft.

Mkd. " $\frac{1}{4}$ 536 CS BT"

This cor. lies on westerly slope
approx. 60 ft. west of top of
spur ridge sloping SW. also
sec. 36 cutoff many years ago.

August 16, 1967

J.R.T.
J.H.
D.W.

(Handwritten signature)

#85 O.K. J.W.B.

C.S. File No. 57/1013