

Renew $\frac{1}{4}$ 535/536 T275 R2W

Fd. O.B.T.s as follows -

12" Now 17" Yew N, 85° W, 11 $\frac{3}{4}$ ft.

2 live - scribe visible on nearly healed
Blaze. good cond.

20"? Now 20" Fir N, 27° E, 45 $\frac{5}{8}$ ft.

Now Down - sawed stump - scar visible
on underside of Decayed Log.

2^d COR. Set 1" I.P. & BRASS CAP
Mkd. " COUNTY SURVEYORS OFFICE
1968 T275 $\frac{1}{4}$ 535/536 R2W " &

MK. New B.T. -

10" Hemlock S, $63\frac{1}{2}^{\circ}$ E, 13 $\frac{3}{4}$ ft.

Mkd. " $\frac{1}{4}$ 536 CS BT "

This COR. Lies 75 ft. S. of
S.W. COR. of clearcut unit
in Sec. 36.

Oct 6, 1968

V. R. Tracy

V.R.T.
F.W.J.
V.P.

#95

C.S. File No. 53/40-79