

Review Standard Cor. To Sec. $\frac{535}{7285} | \frac{536}{7285} T275$ R2W

Fd. O.B.T.S 25 Follows - By

40" Fir (snag) N. 57° E, 36 $\frac{3}{4}$ Ft,

40 ft. high - scribe visible

10" now 16" Fir N. 84° E, 40 $\frac{2}{4}$ Ft,

2 live - shows cor - Rescribe "T275 R2W S35 SC5 BT"

7" now 22" Fir N. 1° W, 44 $\frac{3}{4}$ Ft,

2 live - scribe visible on open place.

Rescribe - "T275 R2W S36 SC5 BT"

2⁺ cor point set 1" I.P. & Brass cap

Mkd. "COUNTY SURVEYOR'S OFFICE

1968 T275 R2W S.C. $\frac{535}{536} T285$ "

This cor. lies on E. side of Red Butte L.O. Road.

OCT 17, 1968

V.R.T.
J.H.
J.P.
F.J.
W.P.

V.R.T. Ray

O.K. J.V.B.

53-728

G.S. File No. 54/40-84