

Renew  $\frac{1}{4}$   $\frac{529}{532}$  T275 R2W

Fd. 2 1/2" Alum. Cap firmly set & properly MKd & o.B.T.s as follows-

12" Now 16" cedar N. 50° E, 11 1/2 ft, Down - old scribe visible & New scribe visible.

6" Now 10" cedar S. 36° W, 19 1/2 ft, alive - scribe visible on nearly healed blaze, we set 6 ft. steel fence post alongside Alum. cap & MK. New B.T. -

8" Hemlock S. 20° E, 31 1/2 ft,

Mkd. "1/4 532 CS BT" No other Live Trees N. of cor in S. 29.

This cor. Lies on moderate northerly slope in clear cut unit.

OCT 23, 1968

V.R.T.  
J.H.  
V.P.

V.R.T. Ray

O.K. J.W.B

#84

C.S. File No. 54/40-96