

Renew $\frac{1}{4}$ 530 | 529 T275 R2W

Fd. Q.B.T. as follows -

24" now 26" Hemlock N. 10° E. 7 $\frac{1}{2}$ ft.

Down - We find " $\frac{1}{4}$ 530" scribe

ON chopped out blaze. This B.T.

Fd. by Forrest appraisal Dept. in 1952.

Also from cor. location we find

hole N. 33° E. 15 $\frac{1}{2}$ ft. & possible

B.T. Down hill & Burned - No scribe fd.

at cor. point set 1" I.P. & Brass cap

Mkd. "COUNTY SURVEYORS OFFICE

1968 T275 $\frac{1}{4}$ 530 | 529 R2W" &

set 6 ft. steel fence post along

side Brass cap. Mkd. New B.T.s -

5" Yew S. 37° E. 7 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 529 CS BT"

5" Yew N. 47° W. 51 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 530 CS BT" (Dying)

7" Fir S. 51° W. 38 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 530 CS BT" (20 ft. high Broken Top)

This cor. Lies in large clear cut

approx 330 ft S. of creek course NE.

Not mtd as in field notes

CS54/40-101

Oct. 31, 1968

48 T275 R. Tray

U.R.T.

J.H.

V.P.

C. S. File No.

O.K.
J.W.B.