

Renew $\frac{1}{4}$ R3W 512/57 T275 R2W

Fd. $\frac{1}{2}$ " I.R. & B.T.s 25 Recorded in Ren. #8

T275 R2W 25 follows - #62-T27-3

10" Now 12" D. FIR S. 57° W. 26[±] ft.

alive - Blaze nearly healed over.

6" Now 8" D. FIR S. 11° E. 21[±] ft.

alive - " $\frac{1}{4}$ 57" scribe visible on

partially healed Blaze. ORIG. N.W.

B.T. Now Burned out stump No scribe

Fd. - only opening facing cor. point.

at cor. point in place of I.R. set 1"

I.P. & BRASS cap MKd. "COUNTY SURVEYORS

OFFICE 1968 T275 R3W $\frac{1}{4}$ 512/57

R2W" - Reset I.R. along side BRASS

cap. This cor. lies on N-S fence

fence line 50 ft. S. of the left

BANK of Little River.

Nov. 8, 1968

V.R.T.
F.W.J.
V.P.

V.R.T. Ray

#99
#107-T27-3

P.K.
J.V.V.B.
C.S. File No. 54/40-108