

Renew Sec. Cor. S111512 T275 R2W

Fd. 1957 C.S. BRASS 25 Recorded in

Ren. # 4 & STUMPS of B.T.S - BURNED

52" R. FIR STUMP N. 57 $\frac{1}{2}$ ° W. 38° ft.

SCRIBE visible on BURNED BLAZE.

58" R. FIR STUMP N. 26° E. 113 $\frac{1}{2}$ ft.

SCRIBE visible on BURNED BLAZE.

Q.B.T.S. Badly BURNED. FROM COR. POINT

We set $\frac{5}{8}$ " I.R. 10° ft. South & 2

$\frac{5}{8}$ " I.R. 15° ft. South & 26° ft.

Steel fence post along side

BRASS cap. The Closing COR.

of Sec. 13 & 14 Bears N. 86° W.

71 $\frac{1}{2}$ ft. This COR. Lies in

clearcut area grown up to dense

GREASEWOOD BRUSH.

Nov. 15, 1968

W.A.T.
F.W.J.
V.P.

V.R. Tracy

O.K. J.W.B.

#103

C.S. File No. 54/40-120