

Renew $\frac{1}{4}$ 58/59 T275 R2w

Fd. 1957 c.s BRASS cap & B.T.

25 follows - (see Rev. #2)

ORIG. 18" Now 30" FIR N. 63° W. 22 $\frac{3}{8}$ ft

alive - good cond. ReBlaze healing.

N.E. Rev. B.T. gone completely due
to clearing & U.S. FS. Housing. No

Trees suitable to East of Line

MK. New B.T. in sec. 8.

11" Cedar S. 58° W. 43 $\frac{8}{8}$ ft.

Mkd. " $\frac{1}{4}$ 58 CS BT"

This cor. Lies in N-S. fence

ON West side of U.S. Govt.

TRAILER PARK.

Dec. 2, 1968

U.B.T.
V.P.

V. R. Tracy

O.K.

J.W.B.

#111

C. S. File No. 54/40-134