

Renew $\frac{1}{4}$ 519/520 T275 R2W

Fd. O.B.T.S 25 Follows -

18" Now 24" cedar S. $33\frac{1}{2}^{\circ}$ W, 13 $\frac{3}{4}$ ft,

2 live - previously opened - no scribe

visible - we open higher & find "14"

scribe & Reverse.

30" Now 36" cedar S. $41\frac{1}{2}^{\circ}$ E, 32 $\frac{3}{4}$ ft,

2 live - shows good scar.

2^d cor point set 1" I.P. & BRASS CAP

Mkd. "COUNTY SURVEYOR'S OFFICE

1968 T275 $\frac{1}{4}$ 519/520 R2W"

& MK. New B.T.S -

10" cedar S. 20° E, 25 $\frac{3}{4}$ ft.

Mkd. " $\frac{1}{4}$ 520 CS BT"

18" Hemlock S. 26° W, 28 $\frac{3}{4}$ ft,

Mkd. " $\frac{1}{4}$ 519 CS BT"

This cor. lies on moderate

Easterly slope approx 130 ft.

South small creek flowing East.

Dec. 9, 1968

U.R.T.
F.W.J.
U.P.

U.R.T. Tracy

O.K.
J.W.B.

0
#116

C.S. File No.

54/40-144