

Review  $5\frac{1}{4}$  S 3 only T275 R2W

Fd. 1957 cad BRASS cap in place

& B.T. as follows

13" now 14" FIR N.  $61^{\circ}$  W. 28  $\frac{1}{2}$  ft.

2 live-face BURNED - we Rescribe

" $\frac{1}{4}$  S 3 CS BT" NO TRACE NE. BT.

Due to Logging. MARK new BT. -

10" D. FIR. N.  $7^{\circ}$  E. 47  $\frac{5}{8}$  ft.

Mkd. " $\frac{1}{4}$  S 3 CS BT"

This cor. Lies 74 ft. E. of

CREEK 6 ft. wide flowing N.W.

The N.  $\frac{1}{4}$  Sec 10 (see Rev. #51)

Bears S.  $60^{\circ}$  E. 47  $\frac{3}{8}$  ft. 2 us. Ply.

Alum. cap. & Live BT.

Dec. 10, 1968

URT

F.W.J.

VP.

UR Tray

D.K.

J.W.B.

#122

U.S. File No.

54/40-147