

Renew Angle Point ON S. LINE S. 32 T 27 S R 24

Ed. unrecorded $\frac{3}{4}$ " I.P. at cor.

point & Q.B.T.S as follows -

orig. 12" now 20" cedar S. 62° E. $5\frac{3}{4}$ ft.

we open & find scribe MKs.

orig. 8" now 12" Hemlock N. 12° W. $13\frac{3}{4}$ ft.

Down & Decaying - previously opened

Blaze rotted away - $\frac{3}{4}$ " I.P. in good

cond. - do not set Brass cap -

MK. New B.T.S -

22" cedar S. 18° E. $6\frac{3}{4}$ ft.

Mkd. "AP CS BT"

18" cedar N. 35° E. $23\frac{3}{4}$ ft.

Mkd. "AP CS BT"

This cor. lies on moderate

southerly slope in old growth

timber.

June 12, 1969

VRT
J.G.H.
V.D.P.

V.R.T. Ray

O.K.
J.W.B.

#140

C.S. File No. 64/40
#66 - 728

-171