

Renew W. $\frac{1}{4}$ S 18 only T275 R1W ^{R2W}

Fd. unrecorded U.S. Plywood Alum.

cap MKd. " $\frac{1}{4}$ S 18 only 1962" & aBT.

25 follows -

orig. 7" Now 9" Hemlock S. 18° E. 11 $\frac{1}{2}$ ft.

lying face Down - we Roll over & Ed.

" $\frac{1}{4}$ S 18 BT" scribe under 40+ years

of over growth - (old field notes

call for Fir.) - No Trace other aBT.

cor. stone called for is Broken

& small piece is MKd " $\frac{1}{4}$ " - we

MARK new BTs -

54" D. Fir STUMP N. 69° E. 29 $\frac{5}{8}$ ft.

Mkd. " $\frac{1}{4}$ S 18 CS BT"

50" D. Fir STUMP S. 22 ° E. 37° ft.

Mkd. " $\frac{1}{4}$ S 18 CS BT"

This cor. Lies on North

slope in old clearcut area.

June 20, 1969

V.R.T.

J.G.H.

V.D.P.

V. R. Tracy

D.K.
5-13-69

141 / 22
90 (R-1)

C. S. File No. 54/40-12