

Renewal 59/53 T325 R6W

Found:

orig BTs

36" D.F. New 12" N70W 16⁷
Front Bank scribe visible 1 1/4 S"

16" D.F. New Rotten Stump S82E 5⁹

Renewal

Set Brass cap at 1/4 cor MKR,
county Surveyors office

T325 R6W

1/4 59/53

1967

New Bearing Trees

12" D.F. N 31 W 16⁷
Scribed 1/4 S 7 CS BT

8" Yew wood S 34 E 23⁷
Scribed 1/4 S 3 CS BT

Note

This cor lies approx. 55° North
of small creek.

9-18-67

~~J.M.D.~~
~~J.P.P.~~
J.C.B.

#97 O.H. J.V.V.B.

C.S. File No. 54/82-1

DIETZEN NO. 385-6