

Renewal

9/10
14/15

T335 R6W

Found:
orig etc.

10" D Fir now stump S32E 12°
Tree broken off. Found Scribe Marks

6" D Fir now stub N53W 22°
Stub flush with ground

Renewal #14

30" D Fir now 31" N15E 21°
Face pitched over

24" D Fir now 24" West 12° (Renewal 12°)
No scribe visible

1" Iron Pipe at Sec cor.

Renewal

New Bearing Trees:

25" D. Fir S25E 8°
Scribed T335 R6W S15 CS BT

15" D. Fir N57W 36°
Scribed T335 R6W S9 CS BT

Revised & Rescribed

24" D. Fir West 12°
Scribed T335 R6W S16 CS BT

(Renewal #14)

10-21-67

J. M. G.
10/21/67
J. C. B.

#38

O.K. J.W.B.

C.S. File No. 54/53-37

DIETZEN NO. 385-6

**FILED
RECEIVED**

OCT 24 1967

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**