

Renew $\frac{1}{4}$ $\frac{27}{34}$ T245 R8W

Fd. 1958 C.S. BRASS cap & BTs

Recorded in Ren. #10 as follows-

5" D. FIR N. $49\frac{1}{2}$ E. 25[±] ft.

Down & Burned - shows " $\frac{1}{4}$ S27 CS"

ON UNHEALED & BURNED BLAZE.

14" D. FIR S. 50° E. 11[±] ft.

Down & Nearly Buried. BRASS

cap is BENT OVER UNDER 24" FIR

Log. MK. New B.T.s -

7" D. FIR N. 41° E. 60[±] ft.

Mkd. " $\frac{1}{4}$ S27 CS BT"

10" D. FIR S. $2\frac{1}{2}$ E. 15[±] ft.

Mkd. " $\frac{1}{4}$ S34 CS BT"

This COR. Lies on Steep East
Slope approx 100 ft South of E-W
Timberline in logged & Burned
Area.

Jan 26, 1967

FILED U.R.T.

RECEIVED
JAN 26 1967

JAN 26 1967

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#51
D.K. J.V.B.

C.S. File No. 54/55