

Renew Sec. Cor. W ^{R₈} $\frac{51}{512}$ | T245 R7W

Ed. B.T.'s Recorded in Renewals
* 13 & 94 - 25 follows -

10" D. FIR S. 69° W. 12 $\frac{1}{2}$ ft.

Now 6 ft. hi-stump - scribe visible.

orig. 20" D. FIR N. 39° W. 51 $\frac{1}{2}$ ft.

Now shattered snag - scribe visible.

8" Now 10" W. FIR S. 5° W. 48 $\frac{1}{2}$ ft.

alive - scribe visible.

7" Now 12" W. FIR N. 61° W. 41 $\frac{1}{2}$ ft.

alive - nearly healed Blaze

No Trace other orig. RTS - we

set 1" I.P. & BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1967 T245

R8W $\frac{51}{512}$ R7W" & set 6 ft. Steel

Fence Post along side BRASS cap.

This cor. lies on Left shoulder
of old Log Road 5 $\frac{1}{2}$ ft. east of
Ditch.

Oct. 10, 1967

V.B. Tracy

V.R.T.
J.H.
V.P.

1005-7248
O.K. J.V.B.
#105-724-7

C.S.F.N. 54 155-18