

Renewal

29/28
32/33

T30-1W

Found:

18" Fir ^{OST's} now 22" snag N55W 25°
 opened for service "BT"

18" Pine now stub S78E 23°
 shows scar

Stump hole S35W 15°
 no trace of NE BT

Renewal

Set Brass cap at sec cor M&A
 county Surveyors office

T305 R1W
 S29/S28
 S32/S33
 1968

DIETZGEN NO. 388-6

New Bearing Trees

17" P. Fir ^{N25W} scried T305 R1W S29 CS BT 23°

20" Cedar ^{N56E} scried T305 R1W S28 CS BT 28°

14" Cedar ^{S28 1/2 E} scried T305 R1W S33 CS BT 23°

21" Cedar ^{S 8 W} scried T305 R1W S32 CS BT 27°

1-2-68

[Handwritten signature]
~~_____~~
~~_____~~

27

O.K. J.W.B.

C.S. File No.

5459-19