

Renewal

12/7

T305 R2W

Found


Stone at sec cor

18" D. Fir Now 25" S 24 W 19°  
Stems good Seat

16" Double P. Fir Now 22" N 55° W 25°  
Stems good Seat

Renewal

Set Brass cap at sec cor MAD  
County Surveyors office




1968

old Bearing Truss OK  
Tagged same

Note

This cor lies 50' South of sec cor



1-17-68

~~J.M.D.~~  
~~J.M.D.~~  
~~J.M.D.~~

#39-T30-W  
#10-R2W

O.K. J.V.V.B.

C.S. File No. 54/59-36

DIETZGEN NO. 385-S