

Renewal

1/6
1/7

T305 R/W

Found

Stone at sec. com

30' D Fir NW 1/4 580 E 66°
East side visible T305 R/W

NE BT Down + Rotten

Renewal

Set Brass cap at sec cor MKD,
County Surveyors office

T305

R		56	R
2	51	57	1
W			W

1948

New Bearing Trees:

9' D Fir
Scribed T305 R/W 57 CS BT 30'

4' Cedar
Scribed T305 R/W 56 CS BT 35'

Note

This cap lies 580 North of
1/12 T302 R/W

1-17-48

~~Handwritten signature~~
Handwritten initials

540-T302-W

4101 R/W O.K. J.W.B.

C.S. File No. 34/59-37

DIETZGEN NO. 385-6