

Renewal

525/530
536/

T30S R1W R1E

Found:

18" D. Fir NW2E 541W 214
Scribe visible "536"

18" D. Fir NW2E 257 (Bel 27")
Shows good scar

Old Mound of stone at cor.
No marks found!

Renewal

Set Brass cap at Sec cor MKB
County Surveyors office

T30S

| | | |
|------|-----|---|
| R | 525 | R |
| 1 | 530 | 1 |
| W | 536 | E |
| 1968 | | |

Old Bearing Trees at Tagged
Same

Note This cor lies 236' South of
1/4 cor 130 only ^{o.k.} T30S R1E

1-21-68

J.M.C.
P.M.C.
W.S.C.

#2-T30-1E
#2-T30-1W

O.K. J.W.B. C.S. File No. 54/59-49

DIETZGEN NO. 385-6