

Renewal

525 | 519
530

7303 R1W

Found:

19" D.F. Fir New Stump 568E 27E
opened for scribe 1/4 530 BT

No trace of NB BT

Also Brass cap at Sec. cov MKD

General Land Office

7303 7303

R 525 | 519 R
W 530 E

1923

No Traces in Area cut unit.

Bearing Stumps:

24" D.F. Fir Stump 58 1/2 E 23°
Drove 3/4" I Rod in center of stump

20" D.F. Fir Stump N 81 1/2 E 20°
Drove 3/4" I Rod in center of stump

Note

This cor lies 236' North of R
1/4 25' only 7303 R1W

A/30 lies approx 100' South +
70' West of Logging Rd. Above
High cut Bank

1-29-68

JMD
R1W
MKD

253

O. N. J. W. B.

25 730-1E

C.S. File No. 54/57-57