

Revised

$\frac{32}{5}$

T305 R1W

Found:

T31

50' S Pipe Now 50' S87E N5^E
Scribe visible $\frac{1}{4}$ S

No Trace of NW BT. Falls
10' old S.K. Rd.

Revised

Set Brass cap at $\frac{1}{4}$ cor MHD,
County Surveyors office

T305 R1W

$\frac{1}{4}$ $\frac{532}{55}$

T315
1968

New Bearing Trees

14" D. Fir S87E 33^E
Scribed $\frac{1}{4}$ S 87E CS BT

15" D. Fir S22E 35^E
Scribed $\frac{1}{4}$ S 5 CS BT

2-5-68

[Handwritten signature]

DIETZGEN NO. 385-6

#57 G.N. J.W.B.
#16 T31-1W

C.S. File No. 54/59-99