

Renewal

$\frac{2}{2}$

T293  
T303 RIW

Found:

18" D. Fir New stump S17E  $\frac{12}{2}$   
open for service "187"

No Trace of NE BT

Stone firmly set at  $\frac{1}{4}$  cor  
MKP  $\frac{1}{4}$  on South Face

Also unrecorded 1967 cap (R.M.)  
MKP

USPC Prod. Corp

T303 RIW

$\frac{1}{4}$   
 $\frac{2}{2}$

RE T2 BT

1967

Renewal

New Bearing Trees

7" R. Fir S17W  $\frac{19}{2}$   
Scribed  $\frac{1}{4}$  S2 CS BT

9" D. Fir S11 $\frac{1}{2}$ W  $\frac{21}{2}$   
Scribed  $\frac{1}{4}$  S2 CS BT

Note: This cor lies approx  
50' North of Logging Rd.

2-7-68

*[Handwritten signature]*

755

O.K. J.W.B.

T29-1W

C.S. File No. 54/59-64

DIETZGEN NO. 385-6