

Renewal

M only

T315 RIW

Found:

28" D. Fir now stump S66E R. (S69E) 165  
scribed for section "1/4 S"

No trace of NE BT.

Also Brass cap at A cor MKD.

General land office

T315 RIW

1/4

1A

1923

Renewal

New Bearing Trees

11" B. Fir S83E 29<sup>3</sup>  
scribed 1/4 SA CS BT

10" Yew N11E 22<sup>4</sup>  
scribed 1/4 SA CS BT

Note

This cor lies 26<sup>±</sup> South of  
5/ only

2-9-60

~~J. W. P.~~  
~~J. W. P.~~  
~~J. W. P.~~

DIETZGEN NO. 385-6

#46

O.K. J. W. P.

G. S. File No. 54/59-66