

Renewal 3 only T.305 R/W

Found

10" S. Pipe Now 13" S 45E 57#
Shows good seam

9" S. Pipe Now 25" N 30W 56#
Shows good seam

Stone out of Place M.D. 1/4

Renewal

Set Brass cap at 1/4 cor M.D.

County Surveyors office

T.295 R/W

1/3
T.305 R/W

1968

New Bearing Tree

10" S. Pipe S 5W 19#
Scribed 1/4 S 3 CS BT

Note: This cor lies west of 39 only
33.9

2-20-68

FILED

RECEIVED

FEB 20 1968

COUNTY SURVEYOR
DOUGLAS COUNTY, OK

D. W. J. W. B.

#9-729-1
#60-730-1

C. S. File No. 54/59-73

DIETZGEN NO. 385-6