

Review COR. #4 of H, E, S, 195 T305 RIW
Fd. old. COR. stone firmly set & mkd
"X" on top & "4 HES 195" on claim side
as called for - The only DBT is
gone - we find River calls to South
& East fit orig call distances good.
at COR. point in place of old COR.
stone - set 1" I.P. & BRASS COP MKD.

"COUNTY SURVEYOR'S OFFICE 1970
T305 COR. #4 L HES 195 RIW"
Reset old stone along side - MARK
New BTs -

10" D. FIR S. 62° 0' W. 4 $\frac{3}{4}$ FT.
MKD. "4 HES 195 CS BT"

9" D. FIR S. 32° 0' E. 17 $\frac{8}{16}$ FT.
MKD. "4 HES 195 CS BT"

Note: This COR. is also The N.
 $\frac{1}{16}$ COR. of Secs - 22 & 23 - & lies on
N.E. slope approx 75 ft. East of
Top of SPUR sloping southerly

Feb 5, 1970

[Handwritten signature]

V.R.T.
J.G.H.
VDP

O.H.
J.W.B.

#124

C.S. File No. 54/59-133

N. 302

"Put in the Name"
WEATHER PROOF

J. I. DARRING CORP.
TACOMA WASH. U.S.A.