

Renew $\frac{1}{4}$ $\frac{1222}{52}$ only T235 R9W

Fd. $1\frac{1}{2}$ " I.P. & BRASS IRON CAP MKD

" $\frac{1}{4}$ 52" - UNRECORDED - AT COR. & O.B.T.S.

AS FOLLOWS -

ORIG. 16" NOW 38" FIR East 23 $\frac{1}{2}$ ft.

alive - shows SCAR - we do not open.

ORIG. 8" NOW 30" FIR West 34 $\frac{3}{4}$ ft.

now down - broken off - stump in place

we find scribe " $\frac{1}{4}$ " - we set 1" I.P.

& BRASS CAP MKD. "COUNTY SURVEYORS

OFFICE 1967 T225 $\frac{1}{4}$ $\frac{1222}{52}$ T235

R9W & MK. New B.T.S. -

16" Maple S. 89° W. 14 $\frac{3}{4}$ ft.

Mkd. " $\frac{1}{4}$ 52 CS BT"

7" D. FIR S. 31° E. 18 $\frac{1}{4}$ ft

Mkd. " $\frac{1}{4}$ 52 CS BT"

Deposit I.P. along side BRASS CAP

This cor. lies on moderate north

slope of ridge.

Dec. 13, 1967

V.R.T.
J.H.
V.P.

V.R. Tracy

~~#16-72-9~~

#39 J.W.B.

C.S. File No.

54/60-12