

Renew Sec Cor. <sup>530</sup> 531 | 532 T225 R9W

Ed. O.B.T.s 2 s follows -

ORIG. 12" Now 20" Fir S. 60° E. 25 <sup>1</sup>/<sub>2</sub> ft

Now snag 15 ft hi - scribe visible on unhealed blaze.

ORIG. 10" Now 12" Fir S. 45° W. 5 <sup>3</sup>/<sub>4</sub> ft.

Now only shattered stump - find Reverse "BT"

1879 BT. 2 10" Now 18" Fir N. 78° E. 14 <sup>5</sup>/<sub>8</sub> ft.

Now shattered stump - find "T225 R9W" scribe

<sup>O.B.T.s</sup> face measurements - Set 1" I.P. &

BRASS cap 2<sup>d</sup> cor. point MK. "COUNTY

SURVEYORS OFFICE 1967 T225

531 | 532 R9W " & MK. New B.T.s -

70" D. Fir S. 65° W. 44 <sup>2</sup>/<sub>8</sub> ft.

Mkd. "T225 R9W 531 CS BT"

24" Hemlock S. 43° E 49 <sup>5</sup>/<sub>8</sub> ft.

Mkd. "T225 R9W 532 CS BT"

18" Hemlock N. 69° E. 24 <sup>2</sup>/<sub>8</sub> ft.

Mkd. "T225 R9W 530 CS BT"

This cor lies on spur sloping SE. in dense brush & Reprod.

Dec. 27, 1967

V.R.T.

J.H.

U.P.

*[Handwritten signature]*

O.V. J.W.B.

C.S. File No.

54/60-19