

Renew $\frac{1}{4}$ 526/525 T225 R9W

Fd. unrecorded $1\frac{1}{2}$ " I.P. & BRASS cap
MKd. " $\frac{1}{4}$ 25/ $\frac{1}{4}$ 526" set at cor. point of Q.B.T.S.

ORIG. 30" Now 36" FIR N. 88° E. 17 $\frac{2}{3}$ ft.

Now Down & laying face Down -

ORIG. 12" Now 30" FIR West 44 $\frac{2}{3}$ ft.

Now Badly decayed STUMP we open from
center of stump & find "45" scribe

& Reverse. 2^d exact cor. point

set 1" I.P. & BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1968 T225

$\frac{1}{4}$ 526/525 R9W " & MK. new B.T.S. -

8" D. FIR S. 51° E. 49 $\frac{3}{4}$ ft.

Mkd. " $\frac{1}{4}$ 525 CS BT"

9" D. FIR S. 11° W. 64 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 526 CS BT"

This cor. Lies on Flat Bench

ON Ridge Top course N. & S.

Deposit I.P. along side BRASS cap.

Jan 22, 1968

URT
J.H.
U.P.

(Signature)

63 O.K. J.W.D.

C.S. File No. 5460-27