

535 | 536 T225 R9W
T225

Renew Closing Cor.

Fd. 1 1/2" I.P. set at cor. point - nearly
flush with ground - UNRECORDED, &

O.B.T.s as follows -

orig. 24" Now 36" FIR N. 44° E. 38 3/4 ft,
Now STUMP - shows SCOR - we do not open.

orig. 36" Now 42" FIR S. 33° E. 17 8/10 ft
Record S. 37° E. - Now STUMP - Burned - we

open & find "2 S" scribe & Reverse -

orig. 36" Now 44" FIR N. 58° W. 29 2/4 ft,
Now STUMP - we open & find "S" scribe.

at cor. point set 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYORS OFFICE 1968

T225 535 | 536 C.C. T225 R9W" &

MARK New B.T.s -

9" D. FIR N. 43 1/2° E. 27 1/4 ft.

Mkd. "T225 R9W 536 C.C.S BT"

9" D. FIR N. 50° W. 74 9/10 ft.

Mkd. "T225 R9W 535 C.C.S BT"

This cor. lies on steep south slope
in old logged area. Deposit old cor.
pipe along side BRASS.

Feb. 7, 1968

U.R.T.
I.P.

457-132-9
W.S. Tracy

OK J.W.B.

C.S. File No. 53/60-31