

New Sec. Co.R.

528	527
533	534

 T235 R9W

Fd. a.B.T.s as follows -

Orig. 30" Fir N. $52\frac{1}{2}^{\circ}$ E. 41 $\frac{1}{2}$ ft.

Now only a small part of shattered stump remains - No scribe fd.

Orig. 10" Now 28" Hemlock S. 82° E. 25 $\frac{1}{2}$ ft.

Now 12 ft. high snag - Reverse scribe visible through hole on backside.

No trace other a.B.T.s - at cor.

point set 1" I.P. & Brass cap

Mkd. "COUNTY SURVEYORS OFFICE

1970 T235

528	527
533	534

 R9W" & MK.

New B.T.s

7" Hemlock S. 20° W. 27 $\frac{3}{4}$ ft.

Mkd. "T235 R9W 533 CS BT"

20" Hemlock S. 44° E. 45 $\frac{1}{2}$ ft.

Mkd. "T235 R9W 534 CS BT"

7" Hemlock N. 76° W. 38 $\frac{1}{2}$ ft.

Mkd. "T235 R9W 528 CS BT"

7" D. Fir N. 40° E. 21 $\frac{1}{4}$ ft.

Mkd. "T235 R9W 527 CS BT"

June 1970

URT

UDP

VR Tray

#57

0.5"
J.W.B.

C.S. File No. 54/60-48