

Not Found:

T32S R0W

1/17

Found Probable car tree

Also correct Bearing & Dist to

L. Oak with very old exc. work

Also Hit Bearing & Dist to where

a Laurel has been cut burnt.

All Trees rotted out no

evidence for renewal

2/1

11/12

Found 1" T. P. P.

50" D. Fir S 19 1/2 W 46"

Bark Scribe visible 32 R-W

& other marks very old

38" D. Fir S 25 E 53'

Shows good scars

No Trace of

21" Fir or 2 laurels

J.M.P.

O.K. J.W.B.

C.S. File No.

54/365

9