

Not Found

1/3

T32S R&M

Found

Large 7" Pipe Down

area Burnt

No Other BT's

Also Found

10" laurel N 53 W 26°

Scribed 1/4 S BT 3571

8" laurel S 59 W 14 E

Scribed 1/4 S BT 3571

These bearings & Dist
are found by just
facing up trees approx.

JMB

3-27-70

71/1/2
D. W. B.