

Renewal

30/29
31/32

T325 RBW

Found

19" D. Fir NOW 3/4" S 67 E 6 1/2
Faint Bark Scribe T RBW S BT

24" Pine (gone) Stump/le S 44 W 23 1/2

2" D. Fir NOW 5/16" N 28 E 20 1/2
Shows Scar

No Trace of NW BT
Renewal

Set Brass cap at Sec Cor NWK.
County Surveyors office

T325 RBW

530 529

531 332

1968

New Bearing Traces

10" Yew N 57 E 5 1/2
Scribed T325 RBW 529 CS BT

11" Yew N 4 1/2 W 4 1/2
Scribed T325 RBW 530 CS BT

24" D. Fir S 56 1/2 W 69 1/2
Scribed T325 RBW 531 CS BT

Reblazed & Rescribed

36" D. Fir S 67 E 6 1/2
Scribed T325 RBW 532 CS BT

S-17-68
~~T325~~
~~RBW~~
~~530~~

DIETZEN NO. 385-6

#900 O.K. J.V.V.B.

C.S. File No. 59/65-114