

Renewal

70

T325 R8W

Found

20" D. Fir cor Tree Now Down
Faint Bark Scribe "S"

18" D. Fir Now Stub N30E 6'±
Faint Bark Scribe "BT"

29" D. Fir Now stump S40E 13'±
No scribe visible

Renewal

Set Brass cap at $\frac{1}{4}$ cor N30E
county Surveyors office

T325 R8W

$\frac{1}{4}$ $\frac{S3}{S10}$

1970

New Bearing Trees

30" D. Fir N78E 13'±
Scribe visible $\frac{1}{4}$ S3 CS BT

1" D. Fir S69W 15'±
Scribed CS BT

No other Trees available
To The South.

Note

This cor lies approx 300±
East of Ravine

#106

D.K. B.
J.W. B.

3-26-70

JMB

JMB

54/65-2

c.s.

DIETZEN NO. 385-6